




Manual



Weight controller type **Flex-CK**

INDUSTRIAL INSTRUMENTATION

Table of contents.

Table of contents.....	2
Explanation of production screen.	3
Wiring connection for Flex-CK model Flex.....	4
Wiring connection for Flex-CK model Flex-2100.....	5
Selection Menu.	6
First use of the indicator.	7
Calibration.....	8
Setup the Checkweigher configuration.....	9
Configuration Parameters.	10
Select/Edit Recipe.....	11
Edit Recipe parameters.	12
Recipe parameters.....	13
Production data.	13
Information.	15
Sequence example.....	16

Explanation of production screen.

Possible Indicator Errors:

- : Indicator not available.
- ===== : Maximum display value exceeded.
- UUUUU : Hardware Under load (loadcell defect?).
- OOOOO : Hardware Over load (loadcell defect?).
- CCCCC : No valid calibration available

- Tare active
- Zero active
- Indicator stable
- Run mode
- Rejector Low output on
- Check OK output on
- Rejector High output on


The screenshot shows a control panel with the following elements and callouts:

- Actual weight:** -0.002 kg. A red circle highlights the minus sign, with a callout labeled "Sign".
- Buttons:**
 - +0+ Zero:** Callout: "Create new zero level".
 - +T+ Tare:** Callout: "Create new Tare level".
 - Return:** Callout: "Return to main menu".
 - Start:** Callout: "Start controller in run mode".
 - Recipe:** Callout: "Select/edit recipe".
- Level Settings:**
 - Low level:** 0,102 kg. Callout: "Actual Low level".
 - High level:** 0,300 kg. Callout: "Actual High level".
- Recipe and Status:**
 - Recipe:** Recipe 01. Callout: "Actual recipe".
 - Status:** Program stopped. Callout: "Actual status".
- Speed Control:** A speed bar with a red arc and a value of 0,0 Pcs/min. Callout: "Actual production speed". A maximum value of 60 is also indicated. Callout: "Speed bar maximum".
- Indicator Row:** A row of seven indicator lights. Callouts from the top list point to these lights: "Tare active", "Zero active", "Indicator stable", "Run mode", "Rejector Low output on", "Check OK output on", and "Rejector High output on".



Wiring connection for Flex-CK model Flex.

Loadcell connection,
15p sub-D Female:


1. + Excitation
2. + sense
3. - Excitation
4. - Sense
5. + Signal
6. - Signal
- Housing. Shield



Digital Outputs:




Loadcell connection




AC Power supply
230 Vac 50/60 Hz

Digital Inputs:





- Input 1: Start (option)
- Input 2: Stop (option)
- Input 3: Start Check
- Input 4-8: Not used

Wiring connection for Flex-CK model Flex-2100.




Digital Outputs:

AC Power supply
230 Vac 50/60 Hz



Digital Inputs:




Input 1: Start (option)
Input 2: Stop (option)
Input 3: Start Check
Input 4-8: Not used

Selection Menu.


From the Selection menu it's possible to enter the several Screens.

The Configuration and System setting are locked by a password, log-in with the Log-in button first. To log-out, press the Log-out button. The overall password is "25630".

Screen if Configuration and System settings are disabled:




Screen if Configuration and System settings are enabled:



First use of the indicator.


Before using the controller, please setup the internal indicator first.

Login first to enter the System settings,
Default no password is selected.
The overall password is “25630”.



Calibration.

To calibrate the indicator, follow the next steps:



Enter the “CAL” code and press OK. This “CAL” code is shown in the right upper corner.

Delete all old calibration points. Make sure all points are deleted.

Make sure the weigher is empty and press the “+Activate” button to save the zero point

Press “EDIT” and put a reference weight on the weigher. Enter the weight of the reference weight and press OK.

To save the second point, press the “+Activate” button.

Setup the Checkweigher configuration.

Before using the controller, please setup the configuration for your application first.

Login first to enter the System settings,
Default no password is selected.
The overall password is "25630".

Press the blue "Edit" fields to enter the needed values.
Press the question marks to open information about the parameter.
Press the "OK" button to return to the previous screen and save the settings.

Open parameter information

Edit parameters

Factory settings:

Stability	:OFF
Hold time	:0.00 sec (disabled)
Display hold time	:2.00 sec
Max. Speedbar	:120 pcs/min
Password	:0 (disabled)

Quit without saving

Quit and save


Configuration Parameters.

Stability

Weigher stability (Check delay time) can be switched on or off. It selects the type of delay time before sampling starts.

This parameter works together with the H-Time.


OFF = No delay
H+S = First H-Time then Stable
H = Only H-Time
H/S = H-Time or Stable
S+H = First Stable then H-Time



H-Time

This is the time the controller waits before sampling starts.


The H-Time works together with the stability parameter.



Display Hold


After sampling is finished the display hold time starts. The sampled value will be frozen on the display for this time. After this time the display is "Live" again.

When a new package arrives during this time the hold time will be stopped.




Max. Speedbar

The max value of the speedbar on the production screen.



Password

Password to protect the system settings, configuration setting and edit recipe parameters. When this parameter is set to zero no password is active.



Select/Edit Recipe.

To select a recipe, press the “recipe” button from the production screen.

Select a recipe by pressing on the recipe name in the blue fields.


Use the scroll bar to select the next recipes.

The screen will automatically return to the production screen after selection.

To edit a recipe Press the recipe number in the gray fields.


To enter the recipe edit screen the user must be logged in.

To return to the production screen without changes, press the “Return” button.




Edit Recipe parameters.










To edit the recipe name, press the recipe name button.
 To edit a recipe parameter, press the value in the blue fields.
 Press the question marks to open information about the parameter.
 To return to the previous screen and save the recipe, press the "Return" button.



Use the scroll bar to enter the next values.



Recipe parameters.

 Low level	X
If the checked weight is below this value, the package will be rejected by output low.	
 High level	X
If the checked weight is above this value, the package will be rejected by output high.	
 Sample amount	X
Sample amount is the amount of samples to take during the check of the package.	
 Correction	X
With the Correction factor it's possible to correct the fault caused by the dynamic caristics of the machine.	
Correction is possible from 0,00 to 200,00 %.	
100,00 % means no correction	
 Delay time low	X
Delay time for output low after low level detection.	
 Hold time low	X
Hold time for output low after activating the output.	
 Delay time high	X
Delay time for output high after high level detection.	
 Hold time high	X
Hold time for output high after activating the output.	
 Analogue Speed	X
Set the value for the analogue output, in 0,01%	

Production data.


To view the total checked values, press the “production data” button.

To reset the subtotals, press the Subt.” Button

To reset the totals and subtotals, press the “Total” button.

Press the Question marks to open information about the parameter.

To return to the previous screen, press the “Return” button.



Amount high [X]

The amount high shows the total pieces of the too high checked packages.

Weight OK [X]

The weight OK shows the total weight of the OK checked packages.

Amount low [X]

The amount low shows the total pieces of the too low checked packages.

Weight low [X]

The weight low shows the total weight of the too low checked packages.

Amount OK [X]

The amount OK shows the total pieces of the OK checked packages.

Weight high [X]

The weight high shows the total weight of the too high checked packages.

Standard deviation [X]


The standard deviation shows how much variation there is from the average.
A low standard deviation indicates a high repeatability.


Average [X]

This is the average value from the checked OK values.
The average should be as close as possible to the Setpoint.

Information.

To view the Penko contact information, press the “information” button from the selection menu.



Sequence example.**Sequence:**

1. Start.
2. Wait for Start
3. Start Check (Input 3).
4. Check busy ON
5. Wait for stable and Holdtime parameter.
6. Take amount of Samples.
7. Check if weight is too low
 - a. No, to point 8
 - b. yes, start Delay time low
8. Check if weight is too High
 - a. No, to point 9
 - b. Yes, start delay time high
9. If weight OK, output OK ON
10. Check busy OFF
11. Dosing ready ON.
12. Wait till input start OFF.
13. Dosing ready OFF.
14. Restart.