PENKO Engineering B.V.

Your Partner for Fully Engineered Factory Solutions



Manual: SIGMA4 Smart Junction Box



IMPORTANT SAFETY INFORMATION READ THIS PAGE FIRST!

PENKO Engineering B.V. manufactures and tests its products to meet all applicable national and international standards. It is vital that this instrument is correctly installed, used, and maintained to ensure it continues to operate to its optimum specification.

The following instructions must be adhered to and incorporated into your safety program when installing, using, and maintaining PENKO products. Failure to follow the recommended instructions can affect the system's safety and may increase the risk of serious personal injury, property damage, damage to this instrument and may invalidate the product's warranty.

• Read the instructions fully prior to installing, operating, or servicing the product. If this Instruction Manual is not the correct manual for the PENKO product you are using, call 0031(0)318-525630 for a replacement copy. Keep this Instruction Manual in a safe place for future reference.

• If you do not fully understand these instructions, contact your PENKO representative for clarification.

• Pay careful attention to all warnings, cautions, and instructions marked on and supplied with the product.

• Inform and educate your personnel about the correct installation, operation, and maintenance procedures for this product.

• Install your equipment as specified in the installation instructions of the appropriate Instruction Manual and as per applicable local and national codes. Connect all products to the proper electrical sources.

• To ensure correct performance, use qualified personnel to install, operate, update, program, and maintain the product.

• When replacement parts are required, ensure that qualified technicians use replacement parts specified by PENKO. Unauthorized components and procedures can affect the product's performance and may affect the continued safe operation of your processes. The use of non-specified 'look-alike' substitution parts may result in the risk of fire, electrical hazards, or improper operation.

• Ensure that all equipment doors are closed and protective covers are in place, except when maintenance is being performed by qualified persons, to prevent electrical shock and personal injury.



WARNING

ELECTRICAL SHOCK HAZARD

Installing cable connections and servicing this instrument require access to shock hazard level voltages which can cause death or serious injury.

Disconnect separate or external power sources to relay contacts before commencing any maintenance.

The electrical installation must be carried out in accordance with CE directions and/or any other applicable national or local codes.

Unused cable conduit entries must be securely sealed by non-flammable blanking plates or blind grommets to ensure complete enclosure integrity in compliance with personal safety and environmental protection requirements.

To ensure safety and correct performance this instrument must be connected to a properly grounded, three-wire power source.

Proper relay use and configuration is the responsibility of the user.

Do not operate this instrument without the front cover being secured. Refer any installation, operation or servicing issues to qualified personnel.

WWW.PENKO.COM

PENKO Engineering B.V. is an ETC Company

Email: info@PENKO.com



Table of Contents

Int	Introduction				
1	Overview				
2	Con	nect	ions and options	8	
	2.1	Inst	rument connection	8	
	2.2	Loa	d cell and TEDS connection	9	
	2.3	SIG	VA4 USB connection1	1	
3	PC a	appli	cations1	2	
	3.1	PDI	Client1	2	
	3.2	Pi N	1ach II1	3	
4	Con	figur	ation14	4	
	4.1	SIG	MA4 Live data14	4	
	4.1.	1	Sensors1	5	
	4.1.	2	Sensor Data (hex)10	6	
	4.1.	3	Load cell inputs1	7	
	4.2	102	0 configuration1	8	
	4.2 4.2.	102 1	0 configuration	8 8	
	4.2 4.2. 4.2.	102 1 2	0 configuration	8 8 1	
	4.2 4.2. 4.2. 4.2.	102 1 2 3	0 configuration	8 8 1 3	
	4.2 4.2. 4.2. 4.2. 4.2.	102 1 2 3 4	0 configuration	8 8 1 3	
	4.2 4.2. 4.2. 4.2. 4.2. 4.2.	102 1 2 3 4 5	0 configuration	8 8 1 3 1 6	
	4.2 4.2. 4.2. 4.2. 4.2. 4.2. 4.2.	102 1 2 3 4 5 6	0 configuration	8 8 1 3 1 6 9	
5	4.2 4.2. 4.2. 4.2. 4.2. 4.2. 4.2. Star	102 1 2 3 4 5 6	0 configuration	8 1 3 6 9 7	
5	4.2 4.2. 4.2. 4.2. 4.2. 4.2. 4.2. 5.1	102 1 2 3 4 5 6 rtup Nev	0 configuration	8 1 3 1 6 9 7 7	
5	4.2 4.2. 4.2. 4.2. 4.2. 4.2. 5.1 5.1	102 1 2 3 4 5 6 tup Nev Loa	0 configuration	8 1 3 1 6 9 7 7 7	
5	4.2 4.2. 4.2. 4.2. 4.2. 4.2. 5.1 5.1 5.2 5.3	102 1 2 3 4 5 6 tup Nev Loa	0 configuration 1 Communication settings 1 Load cell selection 2 Load cell test 2 Load cell history overview 3 Test results in event log 3 TEDS calibration 3 messages 4 v Junction box 4 dcell changed 4	8 1 3 1 6 9 7 7 8	
5	4.2 4.2. 4.2. 4.2. 4.2. 4.2. 5.1 5.1 5.2 5.3 5.4	102 1 2 3 4 5 6 tup Loa Jun Mes	0 configuration 1 Communication settings 1 Load cell selection 2 Load cell test 2 Load cell history overview 3 Test results in event log 3 TEDS calibration 3 messages 4 v Junction box 4 dcell changed 4 ssages on PC 4	8 1 3 1 6 9 7 7 8 9	
5	4.2 4.2. 4.2. 4.2. 4.2. 4.2. 5.1 5.1 5.2 5.3 5.4 Bac	102 1 2 3 4 5 6 tup Loa Jun Mes kup a	0 configuration 11 Communication settings 11 Load cell selection 2 Load cell test 2 Load cell history overview 3 Test results in event log 31 TEDS calibration 31 messages 4 v Junction box 4 dcell changed 4 ctionbox error 4 and Restore 5	8 1 3 1 6 9 7 7 8 9 0	



	6.2	Restore	52
	6.3	Backup Info	56
7	Spe	cifications	58



Introduction

The PENKO SIGMA4 Junction Box is a connection box for up to four load cells. The box supports regular and TEDS (Transducer Electronic Data Sheet) load cells. The box can be added to a PENKO 1020 device through the RS422 interface. Adding the box to a PENKO indicator adds the following functionality:

- Calibration by means of TEDS (Transducer Electronic Data Sheet)
- Connecting multiple load cells
- Measuring each individual load cell to determine defects
- Disconnecting defective load cells
- Load cell test measurements can be logged to determine deterioration over time.
- Backup storage of all instrument settings in the Junction box
- On installing a new instrument of the same type, the backup from the Junction Box can be programmed into the instrument.



1 Overview



Number	Description
1	Load cell + TEDS interface 1
2	Load cell + TEDS interface 2
3	Load cell + TEDS interface 3
4	Load cell + TEDS interface 4
5	Instrument connection to connect the PENKO indicator
6	USB A for direct PC communication
7	Power and Communication indicator



2 Connections and options

This chapter describes the connections of the SIGMA4 Smart Junction Box.

2.1 Instrument connection

Connect the SIGMA4 Smart Junction Box to a PENKO indicator using the junction box instrument connection and the PENKO device load cell connection + RS422 connection.



Number	Description
1	+Excitation
2	-Excitation
3	Shield
4	A
5	В
6	+Signal
7	-Signal

Connections:

SIGMA4	PENKO indicator
1	Load cell +excitation
	Load cell +sense
2	Load cell -excitation
	Load cell -sense
3	Load cell shield (any pin from 9 - 15 or case)
4	RS422 pin 1 + 6
5	RS422 pin 4 + 9
6	Load cell +signal
7	Load cell -signal



Connection example PENKO 1020 indicator:



2.2 Load cell and TEDS connection

Up to four load cells can be connected.





Number	Description
1	+Excitation
2	-Excitation
3	Shield
1	T+ (TEDS)
2	T- (TEDS)
3	+Signal
4	-Signal

All four load cells can be a regular load cell or a TEDS load cell. If a TEDS interface is connected, the PENKO indicator detects this automatically.

Load cell connection. The TEDS interface is optional.



2.3 SIGMA4 USB connection

The USB interface is used for communication with PENKO configuration software. This socket accepts a USB-B type connector.



Before connecting the device to a computer using USB, make sure the USB driver is installed. The driver is included in the PENKO configuration PC applications, see chapter PC applications.



3 PC applications

For easy configuration and monitoring, two PC applications are available as download. PDI Client and Pi Mach II. In the following chapters, Pi Mach II is used to demonstrate the SIGMA4 Smart Junction Box functionality.



3.1 PDI Client

PDI client is a small cross-platform application that only works with USB communication. It can run on any operating system that runs Java Runtime Environment (JRE). All device properties are shown in a tree structure and can easily be edited.

Elle Protocol Help PENKO Data Interface PENKO Data Interface Properties Pane Digital inputs Function 1 HOLD Function 2 PEAK RESET Function 3 VALLEY RESET Valley RESET Function 1 Function 2 Function 3 Function 1 Function 1 Function 1 Function 3 Function 3 Function 1 Function 3 Function 1 Function 3 Function 4 Function 4 Function 4 Function 4 Func	PDI Client - COM13				
PENKO Data Interface Properties Pane V PENKO 1020 Name Name Start Quick setup Enable Full setup Function 1 Enable Full setup Function 2 PENKO System Function 3 VALLEY RESET Function 3 Function 1 Function 3 Function 2 Function 3 Function 1 Function 3 Function 3 Function 1 Function 1 Function 3 Function 3 Function 1 Function 3 Function 1 Function 3 Function 1 Function 3 Function 3	Eile Protocol Help				
PENKO PENKO 1020 Name Start Quick setup Enable Full setup Enable Full setup Enable Full setup System System Setup Service Indicator Communication Function 1 Function 2 Passwords Passwords	Properties Pane	PENKO Data Interface Properties Pane			
Screen Screen	Properties Pane Digital inputs Function 1 HOLD Function 2 PEAK RESET Function 3 VALLEY RESET	PENKO Data Interface			
Refrech Discover ready		Pafrach			
	Discover ready				



USB driver and user manual are included in the download



3.2 Pi Mach II

Pi Mach II is a comprehensive Windows application that works with USB and Ethernet communication and has more functionality compared to PDI Client. The tree structure configuration of PDI Client is available in this program. Other features are backup and restore, firmware updates and a build in oscilloscope to analyze signals for different filter settings.

🕂 IdCode: 0625, Device Version: 01.03, Build: 03, Serial: 12345678, Module Version: 00.00, Build: 00, Project: C:\Penko Engineering B.V\Pi Mach II\ 📃 💷					
File Project Environment View Tools Help					
💕 On-Line 🛛 🛞 Eirmware Update Manager 🚡 Program Builder 🍓 Flex Builder 📄 <u>W</u> atches 🗐 E <u>x</u> it					
📗 🖳 Display 🛛 🕨 Control 🌒 Tasks 🛛 у I/D 🗰 Indicator & Registers 📼 Labels 🚝 I	R <u>e</u> sults 🛛 🏭 Pri <u>n</u> ter Layout 进) Printer Ticket 🛛 🕓 <u>C</u> lock 🗠 <u>S</u> cope	🌮 Manage		
□- PENKO □- PENKO 1020 □- 1.1.1 Name =	Class: PENKO.PENKO 1020.System Setup.Digital inputs Path: 1.1.3.4				
- 1.1.2 Start Quick setup - 1.1.3 Enable Full setup B- Live	Function 1	HOLD			
ia- System ⊟- System Setup	Function 2	PEAK RESET			
Service Indicator	Function 3	VALLEY RESET			
Communication Digital Inputs Digital outputs					
	Discover Impo	ort Properties (CSV)	Apply		
ACTIVE USB	Alive: Hours: 2	Min: 46 - Time-up: Hours: 2 Min: 46 - Re	sets: 0		



USB driver and user manual are included in the download



4 Configuration

This chapter describes all configuration settings. All examples are made with the PENKO 1020 indicator and PENKO Pi Mach II software.

4.1 SIGMA4 Live data

Although the configuration of the SIGMA4 Junction Box is done via the connected indicator, the box itself provides some basic live data. Make sure Pi Mach II and the USB driver are installed properly as described in the Pi Mach II user manual. Open Pi Mach II and open Manage. If a USB device is connected, this device will automatically be connected.







The left screen shows the device configuration in a tree structure. The right screen shows the properties of the selected item in the left screen. For example the live load cell information:



4.1.1 Sensors

The Sensors node provides various sensor data.

Select one of the four ports:





Read the TEDS information of the selected port:



4.1.2 Sensor Data (hex)

The Sensor Data node provides the raw hexadecimal TEDS sensor data:

000	c3 1f 00 81 00 00 00 00
008	00 00 00 00 00 84 38 00
010	00 84 38 00 00 00 00 00
018	00 00 00 00 00 48 42 02
020	00 48 42 02 00 00 00 bc



4.1.3 Load cell inputs

The Load cell inputs node provides the input status of the four inputs and the possibility to enable or disable the inputs:





4.2 1020 configuration

The configuration of the junction box is done with the connected indicator. This can be done on the device or with the computer.



4.2.1 Communication settings

The indicator and junction box communicate using the RS-422/RS-485 port and the TP-Master protocol. This protocol is enabled by default in the indicator. By changing this protocol, the communication with the junction box is disabled.

Setting:

Parameter	Value
Protocol	TP Master
Address	0
Stopbits	1
Parity	None
Baudrate	38400
Indicator	0

4.2.1.1 Settings on the 1020 instrument:







When TP-MASTER is selected, only the protocol setting is actually used. The other settings are not used.



4.2.1.2 Settings on PC using 1020 with Pi Mach II:

Select the PENKO 1020 node and click Enable Full Setup:

⊡- PENKO □- PENKO 1020 1.1.1 Name =	Class: PENKO.PENKO 1020 Path: 1.1	
… 1.1.2 Start Quick setup … 1.1.3 Enable Full setup ⊡ Live	Name	
⊞- System ⊞- System Setup		Start Quick setup
⊡. Control ⊟. Access		Enable Full setup
1.2.2 Status = Loadcell changed SIGMA4 Backup Info Jiagnostic Tinuts		
⊕ History ⊕ TEDS		

Go to System Setup - Communication - RS422:

E- PENKO	Protocol	TP-MASTER
- 1.1.1 Name = - 1.1.2 Start Quick setup	Address	0
- 1.1.3 Enable Full setup ⊡ Live	Stopbits	1
⊡- System ⊟- System Setup	Parity	None
. Service ⊕ Indicator	Baudrate	38400 💌
	Indicator	0
Ethernet BusLink Er RS232 ■ RS232		
E CAN		

When TP-MASTER is selected, only the protocol setting is actually used. The other settings are not used.



4.2.2 Load cell selection

All four load cells can be enabled or disabled manually.

4.2.2.1 Selection on the 1020 instrument:





read



an ETC Company





'Store Input Config' stores the currently selected load cells as default. This way, after power on only the selected load cells are connected.

'Restore Input Config' selects the previously stored setting and switches the inputs accordingly.

4.2.3 Load cell test

The connected load cells can be automatically tested one by one. If a load cell has a significant deviation, it is marked as suspicious. If more load cells have a significant deviation, all will be marked as suspicious.

4.2.3.1 Quick test

The load cell test can be started directly from the main screen.

A controller already has to be in STOP mode (by pressing arrow down). An indicator can always access the load cell test:





an ETC Company

Before testing, the TEDS data is read

4.2.3.2 Load cell test on the 1020 instrument:



The load cell test starts

This test takes about 12 seconds for each load cell. There are 3 stages to each load cell test.



- 1. During the first 2 seconds of the test, the instrument is checking for an open connection which could indicate defects in the load cell wiring.
- 2. Then there is a 5 second wait to get a stable reading. This also accounts for the filter settings of the instrument.
- 3. During the last 5 seconds, the load cell average and variation are measured. During measurement, the current measured value is shown. After this stage the average value remains on screen as other load cells are tested.

During testing, the current mV value is shown by default. After completion of the test cycle the load cell test evaluation is also shown.

Examples:





Signal in mV	Test Loadcells 🛛 🕘	This shows the in the load cell
	Testing Loadcell 1	output signal in mV. The 1020 uses
	Signal	a 5V excitation voltage
	1: 0.4048 mV 🖌 🗸	
	2: X	
	3: 🗙	
	4: 🗙	
	▲ ▼ < > +T+ +0+ INTER ESC CAL:135	
Variation in mV	Test Loadcells 🕘	This shows the variation in the load
	Testing Loadcell 1	cell output signal during the last 5
	Variation	seconds of the load cell test. This
	1: 0.0000 mV 🖌 🗸	number should be close to 0. Large
	2: 🗙	numbers can indicate electrical
	3: 🗙	coll defect
	4: 🗙	
	AV () +T+ +0+ INTER ESC CAL: 135	
Signal in mV/V	Test Loadcells 🕘	This shows the in the load cell
	Testing Loadcell 1	output signal in mV/V. This is the
	Signal	basic measurement unit of the
	1: 0.0809 mV/V 🛛 🗸	instrument.
	2: 🗙	
	3: 🗙	
	4: 🗙	
	AV () +T+ +0+ INTER ESC CAL: 135	
Weight	Test Loadcells 🕘	This shows the measured weight on
	Testing Loadcell 1	the loadcell. When multiple
	Weight	loadcells are connected in parallel,
	1: 1.221 kg 🗸	the resulting weight is the average
	2: ×	of all 4 loadcells.
	3: ×	
	4: ×	
	AV <> T+ +0+ O TAC:6 ENTER ESC CAL:135	



% of maxload	Test Loadcells 🛛 🕘	This shows load on the load cell as
	Testing Loadcell 1	a percentage of its rated maximum
	% of Max.Load	load
	1: 11.6% 🖌	
	2: ×	
	3: 🗙	
	4: ×	
	▲ ▼ < > • T+ •0+ • • • • • • • • • • • • • • • • •	
% of total load	Test Loadcells 🕘	This shows load on the load cell as
% of total load	Test Loadcells 🛛 Testing Loadcell 1	This shows load on the load cell as a percentage of the total load on
% of total load	<mark>Test Loadcells ①</mark> Testing Loadcell 1 % of Total Load	This shows load on the load cell as a percentage of the total load on the functioning load cells
% of total load	Test Loadcells 🔄 Testing Loadcell 1 % of Total Load 1: 100.0% 🗸	This shows load on the load cell as a percentage of the total load on the functioning load cells
% of total load	Test LoadcellsITesting Loadcell 1% of Total Load1: 100.0%2:X	This shows load on the load cell as a percentage of the total load on the functioning load cells
% of total load	Test LoadcellsITesting Loadcell 1% of Total Load1: 100.0%2:3:X	This shows load on the load cell as a percentage of the total load on the functioning load cells
% of total load	Test LoadcellsITesting Loadcell 1% of Total Load1: 100.0%2:3:4:	This shows load on the load cell as a percentage of the total load on the functioning load cells

Measured values can also show the following errors:

000000	Overload	The load cell input measures a signal that is above its maximum
		measuring range.
uuuuuu	Underload	The load cell input measures a signal that is below its minimum
		measuring range.
сссссс	Calibration Error	This is only shown during weight display when the instrument is
		not calibrated correctly.
	Invalid	Open circuit detect failed. The load cell input measures an open
		circuit or a signal that is above its maximum measuring range.
	No readout	This input has not been tested yet.







is pressed, only the load cells marked with 🗹 are enabled and this setting is

When





is pressed the inputs are restored to their last saved settings.

4.2.3.3 Loadcell test on PC using 1020 with Pi Mach II:

PENKO PENKO 1020 SIGMA4 Junction Box 1.2.1 Search Junction Box	Class: PENKO.SIGMA4 Junction Box.Diagnostic Path: 1.2.3		
 1.2.2 Status = Loadcell changed ■ SIGMA4 Backup Info 	Input 1		
□ Diagnostic 1.2.3.1 Input 1 =	Input 2		
 	Input 3		
 	Input 4		
	Average	0,0000 mV	
	Status	-	
		Test Start	
		Test Stop	
⊕ Variation ⊕ Deviation	Input 1 result	-	
	Input 2 result	-	
⊞-% of Max.load ⊞-% of Total Load	Input 3 result	-	
⊕- Inputs ⊕- History	Input 4 result	-	
	Live Signal	0,0119 mV	

- Input 1 to Input 4 show signal in mv from each load cell. When the signal is out of range, no load cell is connected or a test has not yet been performed, '-----' is shown.
- Average shows the average of all load cells that are generating a valid signal
- Status shows which loadcell is currently being tested
- Test Start and Test Stop are used to start and stop the load cell test
- Input 1 result to Input 4 result show the test results after evaluation. This information is updated after all 4 inputs have been tested



• *Live signal* shows the current input signal to the 1020. During the first phase of the test this value jumps up due to the open circuit test.

The submenus under Diagnostic can also be opened to show the Variation, Deviation from average, mV/V signal, weight, % of maxload and % of total load of each load cell.

A large variation can indicate unstable construction, vibration, bad cabling or moisture ingress into the load cell electronics.



1 2 1 Soarch Junction Box				
1.2.2 Status Landard shareed				
1.2.2 Status = Loadcell changed				
- 1.2.3.1 Input 1 = 0,0118 mV				
- 1.2.3.2 Input 2 =				
1.2.3.3 Input 3 =				
1.2.3.4 Input 4 =				
- 1.2.3.5 Average = 0,0118 mV				
- 1.2.3.6 Status = Done				
- 1.2.3.8 Test Stop				
- 1.2.3.9 Input 1 result = OK				
- 1.2.3.10 Input 2 result = Fail				
- 1.2.3.11 Input 3 result = Fail				
- 1.2.3.13 Live Signal =	L			
Variation				
- 1.2.3.1.1 Input 1 variation = 0,0001 mV				
1.2.3.1.2 Input 2 variation =				
- 1.2.3.1.3 Input 3 variation =				
1.2.3.1.4 Input 4 variation =				
- 1.2.3.2.1 Deviation 1 = 0,0000 mV				
1.2.3.2.2 Deviation 2 =				
1.2.3.2.3 Deviation 3 =				
1.2.3.2.4 Deviation 4 =				
⊟ mV/V				
1.2.3.3.1 Input 1 = 0.0023 mV/V				
1.2.3.3.2 Input 2 =				
1.2.3.3.3 Input 3 =				
12334 Input 4 =				
Weight				
12341 Input 1 = 0.23 lb				
12342 Input 2 =				
1.2.3.4.2 Input 2 -				
1.2.3.4.5 input $3 =$				
12251 mout 1 = 0.2.94				
1.2.3.5.1 Input 1 = 0,2 %				
1.2.3.5.2 Input 2 =				
1.2.3.3.3 Input 3 =				
1.2.3.0.1 input 1 = 100,0 %				
1.2.3.6.2 Input 2 =				
1.2.3.6.3 input $3 =$				
1.2.3.0.4 Input 4 =	1			

Class: PENKO.SIGMA4 Junction Box.Diagnostic Path: 1.2.3		
Input 1	0,0118 mV	
Input 2		
Input 3		
Input 4		
Average	0,0118 mV	
Status	Done	
	Test Start	
	Test Stop	
Input 1 result	ок	
Input 2 result	Fail	
Input 3 result	Fail	
Input 4 result	Fail	
Live Signal		

4.2.4 Load cell history overview

The result of the load cell tests performed on the instrument can be stored in the event log of the indicator. For an overview of a load cells performance, the last 10 test can be retrieved. When testing should always be done when the scale is empty or at the same load. This way changes in the signal over time can be observed.



4.2.4.1 History on the 1020 instrument:





Transducers 🗐	
Transducer 1	ENTER
Transducer 2	
Transducer 3	
Transducer 4	
Average	
▲ ▼ < > ① +T+ +0+ J ⊙ TAC:14 ENTER ESC CAL:19	

Tr	ansdu	cer 1		Ęт	ransdu	cer 2		Ę			
	Date:	Average	Variation	U:	Date:	Average	Variation	U			
01:	24-09-15	0.1205	± 0.0000	m 01	: 24-09-15	0.0673	± 0.0000	m			
02:	24-09-15	000000	± 0.0000	m 02	: 24-09-15	0.0677	± 0.0001	m			
03:	24-09-15	0.1208	± 0.0000	m 03	: 24-09-15	0.0677	± 0.0000	m			
04:	22-09-15	10.0384	± 0.0000	m 04	: 22-09-15	0.0814	± 0.0001	m			
05:	22-09-15	10.0388	± 0.0000	m 05	: 22-09-15	0.0814	± 0.0000	m			
06:	22-09-15	10.0387	± 0.0000	m 06	: 22-09-15	0.0815	± 0.0000	m			
07:	22-09-15	10.0388	± 0.0000	m 07	: 22-09-15	0.0814	± 0.0000	m			
08:	14-09-15	0.1199	± 0.0000	m 08	: 14-09-15	0.0672	± 0.0000	m			
09:	14-09-15	0.1279	± 0.0000	m 09	: 14-09-15	0.0672	± 0.0000	m			
10:	14-09-15	0.1199	± 0.0000	m 10	: 14-09-15	0.0672	± 0.0000	m			
Avg:		4.5293	± 0.0000	m'Av	g:	0.0730	± 0.0000	m			
Tr	angdu	der 3		Em	rangdu	aar A		E a	verage		
Tr	ansdu	cer 3		Ęт	<mark>ransdu</mark>	cer <mark>4</mark>		ĘA	verage		
Tr	ansdu Date:	<mark>cer 3</mark> Average	Variation	<mark>Ет</mark> ण	ransdu Date:	<mark>cer 4</mark> Average	Variation	<mark>ק ק</mark>	verage Date:	Average	Variation
Tr 01:	ansdu Date: 24-09-15	<mark>Cer 3</mark> Average -0.0045	Variation ± 0.0000	<mark>ЕТ</mark> U: m 01	ransdu Date: : 24-09-15	<mark>cer 4</mark> Average 0.1572	Variation ± 0.0000	<mark>[</mark> Д U m 0:	Date: 1: 24-09-15	Average 0.0851	Variation ± 0.0000
Tr 01: 02:	ansdu Date: 24-09-15 24-09-15	cer 3 Average -0.0045 000000	Variation ± 0.0000 ± 0.0000	<mark>ЕТ</mark> U: m'01 m'02	ransdu Date: : 24-09-15 : 24-09-15	cer 4 Average 0.1572 0.1577	Variation ± 0.0000 ± 0.0000	<mark>[</mark> Д U m 0: m 02	Date: 1: 24-09-15 2: 24-09-15	Average 0.0851 0.1127	Variation ± 0.0000 ± 0.0000
Tr 01: 02: 03:	ansdu Date: 24-09-15 24-09-15 24-09-15	cer 3 Average -0.0045 000000 000000	Variation ± 0.0000 ± 0.0000 ± 0.0000	U m 01 m 02 m 03	ransdu Date: : 24-09-15 : 24-09-15 : 24-09-15	Cer 4 Average 0.1572 0.1577 0.1576	Variation ± 0.0000 ± 0.0000 ± 0.0001	[24 10 10 10 10 10 10 10 10 10 10 10 10 10	Date: 1: 24-09-15 2: 24-09-15 3: 24-09-15	Average 0.0851 0.1127 0.1153	Variation ± 0.0000 ± 0.0000 ± 0.0000
Tr 01: 02: 03: 04:	ansdu Date: 24-09-15 24-09-15 24-09-15 22-09-15	Cer 3 Average -0.0045 000000 000000 000000	Variation ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000	U m'01 m'02 m'03 m'04	ransdu Date: 24-09-15 24-09-15 24-09-15 24-09-15 22-09-15	cer 4 Average 0.1572 0.1577 0.1576 0.1574	Variation ± 0.0000 ± 0.0001 ± 0.0001 ± 0.0000	U m 0: m 0: m 0: m 0: m 0:	Date: Date: 1: 24-09-15 2: 24-09-15 3: 24-09-15 4: 22-09-15	Average 0.0851 0.1127 0.1153 3.4257	Variation ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000
Tr 01: 02: 03: 04: 05:	ansdu Date: 24-09-15 24-09-15 24-09-15 22-09-15 22-09-15	Cer 3 Average -0.0045 000000 000000 000000 -0.0045	Variation ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000	U m 01 m 02 m 03 m 04 m 05	ransdu Date: 24-09-15 24-09-15 24-09-15 24-09-15 22-09-15 22-09-15	cer 4 Average 0.1572 0.1577 0.1576 0.1574 0.1573	Variation ± 0.0000 ± 0.0000 ± 0.0001 ± 0.0000 ± 0.0000	U m 0: m 0: m 0: m 0: m 0: m 0:	Date: Date: 1: 24-09-15 2: 24-09-15 3: 24-09-15 4: 22-09-15 5: 22-09-15	Average 0.0851 0.1127 0.1153 3.4257 2.5682	Variation ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000
Tr 01: 02: 03: 04: 05: 06:	ansdu Date: 24-09-15 24-09-15 24-09-15 22-09-15 22-09-15 22-09-15	Cer 3 Average -0.0045 000000 000000 000000 -0.0045 -0.0045 -0.0045	Variation ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000	U m 01 m 02 m 03 m 04 m 05 m 06	Date: 24-09-15 24-09-15 24-09-15 24-09-15 22-09-15 22-09-15 22-09-15	cer 4 Average 0.1572 0.1577 0.1576 0.1574 0.1573 0.1573	Variation ± 0.0000 ± 0.0000 ± 0.0001 ± 0.0000 ± 0.0000 ± 0.0000	U m 01 m 02 m 03 m 04 m 05 m 06	Date: Date: 1: 24-09-15 2: 24-09-15 3: 24-09-15 4: 22-09-15 5: 22-09-15 6: 22-09-15	Average 0.0851 0.1127 0.1153 3.4257 2.5682 2.5682	Variation ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000
Tr 01: 02: 03: 04: 05: 06: 07:	ansdu Date: 24-09-15 24-09-15 24-09-15 22-09-15 22-09-15 22-09-15 22-09-15	Cer 3 Average -0.0045 000000 000000 000000 -0.0045 -0.0045 -0.0045	Variation ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000	U m 01 m 02 m 03 m 04 m 05 m 06 m 06	ransdu Date: 24-09-15 24-09-15 24-09-15 22-09-15 22-09-15 22-09-15 22-09-15	Average 0.1572 0.1577 0.1576 0.1574 0.1573 0.1574	Variation ± 0.0000 ± 0.0000 ± 0.0001 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000	U m 01 m 02 m 03 m 03 m 04 m 05 m 06 m 07	Date: Date: 1: 24-09-15 2: 24-09-15 3: 24-09-15 4: 22-09-15 5: 22-09-15 6: 22-09-15 7: 22-09-15	Average 0.0851 0.1127 0.1153 3.4257 2.5682 2.5682 2.5682	Variation ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000
Tr 01: 02: 03: 04: 05: 06: 07: 08:	ansdu Date: 24-09-15 24-09-15 22-09-15 22-09-15 22-09-15 22-09-15 22-09-15 14-09-15	Cer 3 Average -0.0045 oococoo -0.0045 oococoo -0.0045 -0.0045 -0.0045 -0.0045 -0.0045	Variation ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000	U m 01 m 02 m 03 m 04 m 05 m 06 m 07 m 08	ransdu Date: 24-09-15 24-09-15 24-09-15 22-09-15 22-09-15 22-09-15 22-09-15 22-09-15 14-09-15	Cer 4 Average 0.1572 0.1577 0.1577 0.1576 0.1576 0.1577 0.1576 0.1574 0.1573 0.1574 0.1574 0.1574 0.1574	Variation ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000	U m 01 m 02 m 03 m 03 m 04 m 05 m 06 m 07 m 08	Date: Date: 24-09-15 2: 24-09-15 3: 24-09-15 5: 22-09-15 5: 22-09-15 6: 22-09-15 7: 22-09-15 8: 14-09-15	Average 0.0851 0.1127 0.1153 3.4257 2.5682 2.5682 2.5682 0.0855	Variation ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000
Tr 01: 02: 03: 04: 05: 06: 07: 08: 09:	ansdu Date: 24-09-15 24-09-15 22-09-15 22-09-15 22-09-15 22-09-15 22-09-15 14-09-15	Cer 3 Average -0.0045 oococoo -0.0045 oococoo -0.0045 -0.0045 -0.0045 -0.0045 -0.0045 -0.0031 -0.0032	Variation ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0001	U m 01 m 02 m 03 m 04 m 05 m 05 m 05 m 06 m 07 m 08 m 09	Date: Date: 24-09-15 24-09-15 22-09-15 22-09-15 22-09-15 22-09-15 12-09-15 12-09-15 12-09-15 14-09-15 14-09-15	Cer 4 Average 0.1572 0.1577 0.1576 0.1576 0.1574 0.1573 0.1574 0.1574 0.1574 0.1574 0.1574 0.1574 0.1574	Variation ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000	U m 00 m 00 m 00 m 00 m 00 m 00 m 00 m 0	Date: Date: 1: 24-09-15 2: 24-09-15 3: 24-09-15 4: 22-09-15 5: 22-09-15 6: 22-09-15 7: 22-09-15 8: 14-09-15 9: 14-09-15	Average 0.0851 0.1127 0.1153 3.4257 2.5682 2.5682 2.5682 0.0855 0.0874	Variation ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000 ± 0.0000
Tr. 01: 02: 03: 04: 05: 06: 07: 08: 09: 10:	ansdu Date: 24-09-15 24-09-15 22-09-15 22-09-15 22-09-15 22-09-15 22-09-15 14-09-15 14-09-15	Cer 3 Average -0.0045 -000000 -0.0045 -0.0045 -0.0045 -0.0045 -0.0045 -0.0045 -0.0031 -0.0032 -0.0032	Variation ± 0.0000 ± 0.0000	U m 01 m 02 m 03 m 03 m 04 m 05 m 05 m 06 m 06 m 09 m 09 m 10	Date: Date: 24-09-15 24-09-15 22-09-15 22-09-15 22-09-15 22-09-15 12-09-15 14-09-15 14-09-15 14-09-15 14-09-15	cer 4 Average 0.1572 0.1577 0.1576 0.1574 0.1573 0.1574 0.1574 0.1581 0.1580 0.1580	Variation ± 0.0000 ± 0.0000	U m 0: m 0: m 0: m 0: m 0: m 0: m 0: m 0:	Date: Date: 24-09-15 2: 24-09-15 3: 24-09-15 4: 22-09-15 5: 22-09-15 6: 22-09-15 7: 22-09-15 8: 14-09-15 9: 14-09-15 9: 14-09-15	Average 0.0851 0.1127 0.1153 3.4257 2.5582 2.5682 2.5682 0.0855 0.0855 0.0854	Variation ± 0.0000 ± 0.0000



4.2.4.2 History on PC using 1020 with Pi Mach II:

Searching the log for loadcell data can take a few seconds. It is only retrieved when pressing the 'Retrieve History' button.



After the history retrieval is done, the history overview consists of:

- The date of the last 10 measurements.
- The last 10 measurements for each load cell.
- The variation during the last 10 measurements for each load cell.
- The average of all 4 load cells of the last 10 measurements.
- The variation of the average of all 4 load cells during the last 10 measurements.
- The average value of each load cell over the last 10 measurements.



- History
1 2 5 1 Retrieve History
$= 1.2 \pm 1.1 = 0.6 + 0.000 \text{ m}/$
$1.2.5.1.11 = 00.0010: 00000000 \pm 00.0000000$
$1.2.5.1.2.2 = 06-06-16; 00000000 \pm 00.000000V$
$1.2.5.1.3 = 06-06-16: 00000000 \pm 00.000000V$
$1.2.5.1.4 = 06-06-16: 00000000 \pm 00.0000$ mV
$-1.2.5.1.55 = 06-06-16:00000000 \pm 00.0000$ mV
$-1.2.5.1.6\ 6 = 06-06-16:\ 00000000\ \pm\ 00.0000$ mV
1.2.5.1.9 9 = 06-06-16: 00000000 ± 00.0000mV
-1.2.5.1.10 10 = 06-06-16: 00000000 ± 00.0000mV
1.2.5.1.11 History Average = 00.0000 ± 00.0000mV
🚊 Loadcell 2
1.2.5.2.2 2 = 06-06-16: 07.5084 ± 00.0002mV
1.2.5.2.3 3 = 06-06-16: 07.5085 ± 00.0001mV
1.2.5.2.4 4 = 06-06-16: 07.5086 ± 00.0000mV
$1.2.5.2.5 = 06-06-16$; 07.5085 \pm 00.0000mV
$1.2.5.2.6 = 06-06-16$; $07.5084 \pm 00.0001 \text{mV}$
$1.2.5.2.7.7 = 06-06-16$; $07.5084 \pm 00.0001 \text{mV}$
125288 = 06-06-16; 07 5084 + 00 0001mV
1.2.5.2.6.6 = 0.6.06 - 16! 07.5001 = 00.0000mV
1.2.5.2.5.5 = 00.00101 + 0.00000000000000000000000000
$1.2.5.2.10 = 00 00 10. 07.5007 \pm 00.000100$
- Loadcoll 2
□ Loducell 5
$1.2.5.3.11 = 06.06.16$; 00000000 ± 00.000000
$1.2.5.3.22 = 06-06-16; 00000000 \pm 00.0000000$
$1.2.5.3.3 = 00-00-10; 00000000 \pm 00.000000V$
$1.2.5.3.44 = 06 - 06 - 16:00000000 \pm 00.000000V$
$-1.2.5.3.55 = 06-06-16:00000000 \pm 00.0000$ mV
$1.2.5.3.6 = 06-06-16: 00000000 \pm 00.0000$ mV
-1.2.5.3.7 7 = 06-06-16: 00000000 ± 00.0000mV
-1.2.5.3.10 10 = 06-06-16: 00000000 ± 00.0000mV
- 1.2.5.3.11 History Average = 00.0000 ± 00.0000mV
🖻 Loadcell 4
1.2.5.4.1 1 = 06-06-16: 00000000 ± 00.0000mV
1.2.5.4.4 4 = 06-06-16: 00000000 ± 00.0000mV
1.2.5.4.5 5 = 06-06-16: 00000000 ± 00.0000mV
1.2.5.4.6 6 = 06-06-16: 00000000 ± 00.0000mV
1.2.5.4.77 = 06-06-16; 00000000 ± 00.0000mV
1.2.5.4.8 = 06-06-16; 00000000 ± 00.0000mV
$1.2.5.4.99 = 06-06-16$; 00000000 ± 00.0000 mV
$-1.2.5.4.10\ 10 = 06-06-16:\ 00000000\ \pm\ 00.000000V$
1.2.5.4.11 History Average = 00.0000 ± 00.0000W
1.2.5.5.1 average 1 = 06-06-16: -00 0003 + 00 0001mV
12552 average $1 = 000010$, 00.0003 ± 00.00010
1.2.3.3.2 dverdge 2 - 00 00 10. 07.3004 ± 00.0002110

Class: PENKO.SIGMA4 Junction Box.History.Average Path: 1.2.5.5

average 1	06-06-16: -00.0003 ± 00.0001mV
average 2	06-06-16: 07.5084 ± 00.0002mV
average 3	06-06-16: 07.5085 ± 00.0001mV
average 4	06-06-16: 07.5086 ± 00.0000mV
average 5	06-06-16: 07.5085 ± 00.0000mV
average 6	06-06-16: 07.5084 ± 00.0001mV
average 7	06-06-16: 07.5084 ± 00.0001mV
average 8	06-06-16: 07.5084 ± 00.0001mV
average 9	06-06-16: 07.5084 ± 00.0000mV
average 10	06-06-16: 07.5084 ± 00.0001mV



4.2.5 Test results in event log

The result of the load cell tests are stored in the event log of the indicator.

4.2.5.1 Event log on the 1020 instrument











▲ ▼ <> + + +0+ ↓ ⊙ TAC:174 CAL:2952

Header with date/time



4.2.5.2 Event log on PC using 1020 with Pi Mach II:

⊡ • PENKO ⊡ • PENKO 1020 □ • 1.1.1 Name =	Class: PENKO.PENKO 1020.Ac Path: 1.1.7.3	cess.Event Log
1.1.2 Start Quick setup 1.1.3 Enable Full setup II- Live	Number of entries	3224
⊡- System ⊡- System Setup	Entry Number	3222
⊡ • Control	Record	Data
	Tag/Code	Loadcell 4
□ SIGMA4 Junction Box	Date/Value	0016776.960
- 1.2.2 Status = Loadcell changed	Time/Unit	mV
	UID	2181960187
History		Print
± TED2		

4.2.6 TEDS calibration

The junction box can read out Transducer Electronic Data Sheets (TEDS) information from IEEE1451.4 compliant load cells. The following actions are performed when a TEDS load cell is detected:

- The input number and TEDS ID code are stored as a transducer type
- The Transducer measurement unit is selected as the instrument unit.
- The minimum and maximum electrical value are used to set the zero balance and range
- The maximum force/weight is used to calculate the maximum load
- From the total maximum load, a decimal point position and step size are selected so the readout is 10.000 parts or less

4.2.6.1 TEDS calibration on 1020 device:











After entering the TEDS menu, the indicator requests the TEDS data from the junction box and its connected TEDS chips. When all datasheets are read, the indicator totalizes the data and calculates the calibration data.



When TEDS load cells of different units, ranges or manufacturers are found, the instrument cannot simply add the load cell information and an error is shown. The electronic datasheets of all TEDS load cells can be displayed on a PC using PI.



When one or more compatible TEDS load cells have been found, the suggested indicator settings are shown:





These settings can be changed manually. The suggested Max Load is the addition of the maximum weight from each of the TEDS datasheets plus a small margin.



stores the settings - ESC discards the settings

After storing the settings, the deadload calibration is started.





Enter the weight that is currently on the scale.

When TECSIS TEDS loadcells are connected, the 1020 Sets the factory location. To ensure correct gravity settings the installation location must now be entered.



Enter the Latitude and Elevation of the install location.

The TEDS data is stored as a transducer type and is found in the calibration menu.







The TEDS datasheets are checked on startup, on entering the ' Σ 4 Junction Box' menu or before a load cell test. If the number of TEDS or TEDS ID codes differ from the stored configuration, a warning is displayed:







4.2.6.2 TEDS calibration on PC using 1020 with Pi Mach II:

E PENKO			
		Scan Datasheets	
Junction Box		otan batasneeta	
- 1.2.1 Search Junction Box	Number of TEDS found	0	
		-	
	Status	Ready - Press Update TEDS result	
History		Update TEDS regults	
		opuate reportesuits	

The buttons have the following functions:

- 'Scan datasheets' checks the currently connected TEDS information and shows the suggested settings.
- 'Store Calibration' stores the TEDS information as a Max Load and Load cell calibration. It also stores the suggested step size, decimal position and unit as weigher settings.
- Update TEDS results can be used to view the retrieved TEDS information.

All found TEDS datasheets can be viewed:

PENKO ⊕ PENKO 1020 ⊡ SIGMA4 Junction Box	Class: PENKO.SIGMA4 Junction Box.TEDS.TEDS results.Datasheet 1 Path: 1.2.6.1.1		
	TEDS ID Manufacturer	0023e1aba001 HBM	
History	Model	Z6	
- 1.2.6.1 Scan Datasheets	Serial	0	
 1.2.6.2 Number of YEDS round 1.2.6.3 Status = Ready - Press 1.2.6.4 Update TEDS results TEDS results 1.2.6.1.1 Step = STEP 5 1.2.6.1.2 Decimal Point = 0 1.2.6.1.3 Unit = kg 1.2.6.1.4 Maxload per Cell = 1.2.6.1.5 Total Maxload = 5 1.2.6.1.6 Store Calibration Datasheet 1 	Min.Phys	0,000 kg	
	Max.Phys	50,000 kg	
	Min.Electrical	0,000 mV/V	
	Max.Electrical	2,000 mV/V	
	Maxload	50,000 kg	
	Zero balance	0,000 mV/V	
	Gain	2,000 mV/V	
	Channel	2	



5 Startup messages

When the 1020 is powered up, the connected junction box and load cell TEDS data are checked.

5.1 New Junction box

When a new SIGMA4 junction box is connected to the 1020, the following message appears.



The options are:

- Accept Change. This registers the SIGMA4 junction box in the instrument. The message will not be shown again.
- Backup to Σ4. This copies all settings from the instrument to the SIGMA4 junction box. After a successful backup the junction box will be registered in the instrument. The message will not be shown again.
- Restore from Σ4. This option is only available when the SIGMA4 Junction box already contains a valid backup. After a successful restore the junction box will be registered in the instrument. The message will not be shown again.
- ESC = Cancel. By just pressing the ESC key, the message is dismissed. It will be shown again when the instrument is restarted.

5.2 Loadcell changed



This message is shown when

• The instrument does not contain a TEDS calibration, but TEDS load cells are found



- The instrument contains a TEDS calibration, but no TEDS load cells are found
- The instrument contains a TEDS calibration, but TEDS Load cells are swapped or disconnected
- The instrument contains a TEDS calibration, but load cell's TEDS circuitry or the connection to the TEDS load cell has failed.

This indicates that the weight shown on the instrument might not be correct since the installation has been changed.



Pressing **ESC** dismisses this message but it will be shown again when the instrument is restarted. To end this message

- Restore the installation to its original configuration.
- Check all loadcells and cables
- Do a new TEDS calibration. After this the CAL code will be incremented to show a change in calibration but the new TEDS data is then stored in the instrument.

5.3 Junctionbox error



This message is shown when

- The load cell or communication cables or connectors are disconnected.
- The connection between the instrument and the junction box is broken or shorted. Check the connection cables for both the communication connection and the instrument load cell connection
- A short circuit in the excitation voltage. The load cell excitation voltage is used as power supply for the junction box. The excitation voltage output of the instrument is protected against a short circuit. When the junction box is powered, the LED on the SIGMA4 will flash once per second.







will dismiss the warning until the next power up. Pressing

a configuration without SIGMA4 as default so the warning will not return unless the 1020 was already calibrated using TEDS information.

When the communication with the junction box is restored, this message clears automatically.

5.4 Messages on PC

Using PI, the startup messages are shown in the Junction Box status screen.

PENKO PENKO 1020 SIGMA4 Junction Box 1.2.1 Search Junction Box 1.2.2 Status = SIGMA4 OK SIGMA4 Backup Info Diagnostic Inputs	Class: PENKO.SIGMA4 Junction Box Path: 1.2		
		Search Junction Box	
	Status	SIGMA4 OK	

The following messages can be shown

SIGMA4 OK	Communication with SIGMA4 and TEDS load cells is working.
TPMaster not enabled	The TPMaster protocol is disabled. This stops communication with
	the SIGMA4.
SIGMA4 not found	Communication with SIGMA4 fails.
SIGMA4 changed	The connected SIGMA4 has a different serial number from the
	stored configuration.
Loadcell changed	The number of TEDS chips or the TEDS ID codes have changed from
	the stored configuration.



6 Backup and Restore

The junction box can store a backup of the connected indicator. All indicator settings and calibrations are stored. In case the indicator fails, it can easily be replaced with a new one and restored from the backup.

6.1 Backup

When a SIGMA4 is connected to the 1020 for the first time, a popup is shown. This menu offers the option to make a backup to the SIGMA4.



6.1.1.1 Making a backup on the 1020

A backup of the 1020 device can be made at any moment from the menu:







Press ENTER to start the backup

During backup a progress bar is shown. A complete backup can take up to 6 minutes



6.1.1.2	Making a	backup o	n PC using	1020	with F	Pi Mach II
---------	----------	----------	------------	------	--------	------------

	Class: PENKO.SIGMA4 J Path: 1.2.1	unction Box.SIGMA4 Backup Info
… 1.1.2 Start Quick setup … 1.1.3 Enable Full setup ⊡. Live ⊡. System	SIGMA4 Serial Number	18036015
 ⊡- Control ⊡- Access ⊟- SIGMA4 Junction Box 	Backup ID	0625
 1.2.1 Search Junction Box 1.2.2 Status = Loadcell changed SIGMA4 Backup Info Diagnostic Inputs History TEDS 	Backup Version Backup Date	1.5.3.9.0.5 25-05-2016
	Backup Time	15:13:16
	DOURDY JILE	Backup to SIGMA4
		Restore from SIGMA4
	Progress	0 %

SIGMA4 to start copying data from the 1020 Instrument to the SIGMA4 junction box. This can take up to 6 minutes. The Progress indication will increment from 0% to 100%. When the backup is complete.

6.2 Restore

When an empty 1020 is connected to a SIGMA4 Junction Box containing a valid backup, a popup screen is show during startup:



6.2.1.1 Restoring data on the 1020 instrument

For manually restoring from a backup, the following actions are required:





PENKO an ETC Company Only shown when a SIGMA4 Junction Box is detected. When the SIGMA4 Junction Box does not contain a valid backup, the restore option is disabled.



▲ ▼ < ► ① +T+ +0+ ↓ ③ TAC:11 CAL:344

ENTER restores date from the SIGMA4 Junction BOX into the instrument. ESC cancels the restore



When the firmware version of the new device and the SIGMA4 backup are different, a warning is displayed. It is recommended to keep versions identical since newer firmware can contain different settings. Enter starts the restore. Esc cancels restore

During restore a progress bar is shown. A complete restore can take up to 6 minutes. After restoring, the indicator is restarted using the new settings



6.2.1.2 Restoring data on PC using 1020 with Pi Mach II:

When a backup is stored in the SIGMA4, Its information is shown in the SIGMA4 Backup Info menu.

PENKO PENKO 1020 ··· 1.1.1 Name = ··· 1.1.2 Start Quick setup ··· 1.1.3 Enable Full setup I Live	Class: PENKO.SIGMA4 Junction Box.SIGMA4 Backup Info Path: 1.2.1		
	SIGMA4 Serial Number	18036015	
⊡- System ⊡- Control	Backup Serial	15521078	
 Access SIGMA4 Junction Box 1.2.1 Search Junction Box 1.2.2 Status = Loadcell changed SIGMA4 Backup Info Diagnostic Inputs History TEDS 	Backup ID	0625	
	Backup Version	1.5.3.9.0.5	
	Backup Date	25-05-2016	
	Backup Time	15:13:16	
	Backup Size	491776	
		Backup to SIGMA4	
		Restore from SIGMA4	
	Progress	0 %	

Press *Restore from SIGMA4* to start copying data from the SIGMA4 junction box back to the 1020 Instrument. This can take up to 6 minutes. The Progress indication will increment from 0% to 100%. After restoring, the indicator is restarted using the new settings



6.3 Backup Info

The 1020 can show information about the backup information in the SIGMA4.

6.3.1.1 Backup Info on the 1020 instrument





Backup Info 🛛 🗐	Backup Info 🔄
$\Sigma4$ Serial	Serial Number:
1801102A	48071145
SWID:	Time
0625	12:56:42
Software Version:	Date:
1.5.3.9.0.6	10-05-2016
AV <> +T+ +0+ OF ESC CAL:169	▲ ▼ < > +T+ +0+ OF ENTER ESC CAL:344
Backup Info 🕙	
Date:	
10-05-2016	
Size	
491776	
Device Version	
1.5.3.9.0.3	
▲ ▼ <>	

When no backup is stored in the SIGMA4, only 'Σ4 Serial' is displayed.



7 Specifications

Туре	Description
Electrical	
- Power supply	Powered by 5 to 12VDC load cell supply voltage Current consumption 30-200mA
User interface	
- LED	1 x LED alive heartbeat
Interfaces	
- Load cell - Communication	4 x 6 wire load cell input interface + earth, connector MSTB 4 x TEDS interface, connector MSTB 6 wire load cell output interface + earth, connector MSTB Non-isolated RS485 interface Non-isolated USB device interface
Switches	
- Relay	4x bi-stable Dual pole relay Switching capacity 1A @ 30VDC resistive load
Housing	
 Material Dimensions Cable glands Mounting holes Weight 	Stainless steel enclosure 180 x 150 x 95mm (W x H x D) excluding cable glands 4 x PG9 or M16 for load cells 1 x PG9 or M16 for indicator 157 x 125mm diameter 6mm ±1500g
Environmental	
 Operating temperature Storage temperature Relative humidity Ingress Protection rating 	-10°C to +40°C [14°F to 104°F] -20°C to +70°C [-4°F to 158°F] 40 - 90% non-condensing IP65
Approvals	
- CE - UL	Industrial CE Pending







About PENKO

Our design expertise include systems for manufacturing plants, bulk weighing, check weighing, force measuring and process control. For over 35 years, PENKO Engineering B.V. has been at the forefront of development and production of high-accuracy, high-speed weighing systems and our solutions continue to help cut costs, increase ROI and drive profits for some of the largest global brands, such as Cargill, Sara Lee, Heinz, Kraft Foods and Unilever to name but a few.

Whether you are looking for a simple stand-alone weighing system or a high-speed weighing and dosing controller for a complex automated production line, PENKO has a comprehensive range of standard solutions you can rely on.

Certifications

PENKO sets high standards for its products and product performance which are tested, certified and approved by independent expert and government organizations to ensure they meet – and even – exceed metrology industry guidelines. A library of testing certificates is available for reference on:

http://penko.com/nl/publications_certificates.html



PENKO Professional Services

PENKO is committed to ensuring every system is installed, tested, programmed, commissioned and operational to client specifications. Our engineers, at our weighing center in Ede, Netherlands, as well as our distributors around the world, strive to solve most weighing-system issues within the same day. On a monthly basis PENKO offers free training classes to anyone interested in exploring modern, high-speed weighing instruments and solutions. A schedule of training sessions is found on: www.penko.com/training

PENKO Alliances

PENKO's worldwide network: Australia, Belgium, Brazil, China, Denmark, Germany, Egypt, Finland, France, India, Italy, Netherlands, Norway, Poland, Portugal, Slovakia, Spain, Syria, Turkey, United Kingdom, South Africa, Slovakia Sweden and Switzerland, Singapore. A complete overview you will find on: www.penko.com/dealers

