


PENKO Engineering B.V.

Your Partner for Fully Engineered Factory Solutions



How to...

Connect the SGM750 or SGM850 IND, BLT, CHK or MFL to a FLEX 2100, FLEX or FLEX 2ch. – 4ch.



PENKO

an ETC Company

Table of Contents

General information.....	3
RS232.....	4
Set up the FLEX.....	5
Set up the SGM750/SGM850	5
Checking the connection	7
RS422.....	9
Set up the FLEX.....	10
Set up the SGM750/SGM850	10
Checking the connection	12
Connect the SGM750 or SGM850 to a display	14

PENKO How to...

Connect the SGM750 or SGM850 IND, BLT, CHK or MFL to a FLEX 2100, FLEX or FLEX 2ch. – 4ch.

General information

When the SGM750 or SGM850 is powered by USB (not 24Vdc) the load cell interface, the analog output and Serial communication will not work.


Analoge output (option)

Inputs
Input 1=5khz
18-28Vdc

Outputs
25V/0.5A
AC/DC

Local bus

To PC
Config
software




DC POWER
SUPPLY
18-32Vdc

6-Wire load cell
connection
Vexc=5Vdc

SGM750 or SGM850

Serial connection




With RS232 it is only possible to connect one SGM750 or SGM850 to a FLEX, but if you use RS422 it is possible to connect up to 15 SGM750/SGM850's First we will describe the RS232 connection and then the RS422 connection.

PENKO How to...

Connect the SGM750 or SGM850 IND, BLT, CHK or MFL to a FLEX 2100, FLEX or FLEX 2ch. – 4ch.

RS232

Use a crossover Female to Female Serial cable to connect a SGM750/SGM850 to a FLEX or a FLEX 2ch. – 4ch. If you want to connect a SGM750/SGM850 to a FLEX2100, use the following wiring diagram.




PENKO How to...

Connect the SGM750 or SGM850 IND, BLT, CHK or MFL to a FLEX 2100, FLEX or FLEX 2ch. – 4ch.


Set up the FLEX

Go to **Menu** → **System Setup** → **Port Setup** → **RS232 Port**. Set **Protocol** to “Indicator”, **Address** to “1”, **Baudrate** to “57600”, **Parity** to “None” and **Stopbits** to “1”. Press “Ok” to save settings.



Set up the SGM750/SGM850

Connect the SGM750/SGM850 to a PC using a USB-cable and open Pi Mach II and double click on **SGM750** or **SGM850**, then double click on **System Setup**, double click on **Communication**, double click on **RS232**. Set **Protocol** to “NPV Slave”, **Address** between “1 and 14”, **Stopbits** to “1”, **Parity** to “None”, **Baudrate** to “57600” and **Indicator** “between 1 and 17 the options are described below”. Click on **Apply** to save settings.




PENKO How to...

Connect the SGM750 or SGM850 IND, BLT, CHK or MFL to a FLEX 2100, FLEX or FLEX 2ch. – 4ch.

Indicator number	Function	Description
1	Weigher	The actual weight of the Indicator.
2	Fast Gross	The weight without filtering and Tare.
3	Fast Net	The weight without filtering and Tare deducted.
4	Display Gross	The weight with Display filtering and without Tare.
5	Display Net	The weight with Display filtering and Tare deducted.
6	Tare	The weight of an empty container. Gross – Tare = Net.
7	Peak	The highest point weighted on the Indicator.
8	Valley	The lowest point weighted on the Indicator.
9	Weigher x10	The actual weight of the Indicator with 1 extra decimal point for more accuracy.
10	Fast Gross x10	The weight without filtering and Tare with 1 extra decimal point for more accuracy.
11	Fast Net x10	The weight without filtering and Tare deducted with 1 extra decimal point for more accuracy.
12	Display Gross x10	The weight with Display filtering and without Tare with 1 extra decimal point for more accuracy.
13	Display Net x10	The weight with Display filtering and Tare deducted with 1 extra decimal point for more accuracy.
14	Tare x10	The weight of an empty container. Gross – Tare = Net with 1 extra decimal point for more accuracy.
15	Peak x10	The highest point weighted on the Indicator with 1 extra decimal point for more accuracy.
16	Valley x10	The lowest point weighted on the Indicator with 1 extra decimal point for more accuracy.
17	Sample	The actual sample of the load cell(s) in mV.

Checking the connection

To check if the connection works, use the FLEX and go to **Menu → Status → Indicators → Device**. Now you should see the value of the SGM750/SGM850 between **002 and 016** (depending on the address you have given the SGM). **Address + 1**.



Device number	Address	Value shown on the FLEX
1	1	002
2	2	003
3	3	004
4	4	005
5	5	006
6	6	007
7	7	008

PENKO How to...

Connect the SGM750 or SGM850 IND, BLT, CHK or MFL to a FLEX 2100, FLEX or FLEX 2ch. – 4ch.



Device number	Address	Value shown on the FLEX
8	8	009
9	9	010
10	10	011
11	11	012
12	12	013
13	13	014
14	14	015
15	15	016

PENKO How to...

Connect the SGM750 or SGM850 IND, BLT, CHK or MFL to a FLEX 2100, FLEX or FLEX 2ch. – 4ch.

RS422

Use the wiring diagrams below to connect the SGM750/SGM850 to your FLEX 2100, FLEX, or FLEX 2ch. – 4ch. You can connect up to 15 SGM750/SGM850's.




PENKO How to...

Connect the SGM750 or SGM850 IND, BLT, CHK or MFL to a FLEX 2100, FLEX or FLEX 2ch. – 4ch.


Set up the FLEX

Go to **Menu** → **System Setup** → **Port Setup** → **RS422 Port**. Set **Protocol** to “Indicator”, **Address** to “1”, **Baudrate** to “57600”, **Parity** to “None” and **Stopbits** to “1”. Press “Ok” to save settings.



Set up the SGM750/SGM850


Connect the SGM750/SGM850 to a PC using a USB-cable and open Pi Mach II and double click on **SGM750** or **SGM850**, then double click on **System Setup**, double click on **Communication**, double click on **RS422**. Set **Protocol** to “NPV Slave”, **Address** between “1 and 14”, **Stopbits** to “1”, **Parity** to “None”, **Baudrate** to “57600” and **Indicator** “between 1 and 17 the options are described below”. Click on **Apply** to save settings.



Indicator number	Function	Description
1	Weigher	The actual weight of the Indicator.
2	Fast Gross	The weight without filtering and Tare.
3	Fast Net	The weight without filtering and Tare deducted.
4	Display Gross	The weight with Display filtering and without Tare.
5	Display Net	The weight with Display filtering and Tare deducted.
6	Tare	The weight of an empty container. Gross – Tare = Net.
7	Peak	The highest point weighted on the Indicator.
8	Valley	The lowest point weighted on the Indicator.
9	Weigher x10	The actual weight of the Indicator with 1 extra decimal point for more accuracy.
10	Fast Gross x10	The weight without filtering and Tare with 1 extra decimal point for more accuracy.
11	Fast Net x10	The weight without filtering and Tare deducted with 1 extra decimal point for more accuracy.
12	Display Gross x10	The weight with Display filtering and without Tare with 1 extra decimal point for more accuracy.
13	Display Net x10	The weight with Display filtering and Tare deducted with 1 extra decimal point for more accuracy.
14	Tare x10	The weight of an empty container. Gross – Tare = Net with 1 extra decimal point for more accuracy.
15	Peak x10	The highest point weighted on the Indicator with 1 extra decimal point for more accuracy.
16	Valley x10	The lowest point weighted on the Indicator with 1 extra decimal point for more accuracy.
17	Sample	The actual sample of the load cell(s) in mV.

Checking the connection

To check if the connection works, use the FLEX and go to **Menu → Status → Indicators → Device**. Now you should see the value of the SGM750/SGM850 between **002 and 016** (depending on the address you have given the SGM). **Address + 1**.



Device number	Address	Value shown on the FLEX
1	1	002
2	2	003
3	3	004
4	4	005
5	5	006
6	6	007
7	7	008

PENKO How to...

Connect the SGM750 or SGM850 IND, BLT, CHK or MFL to a FLEX 2100, FLEX or FLEX 2ch. – 4ch.

Device number	Address	Value shown on the FLEX
8	8	009
9	9	010
10	10	011
11	11	012
12	12	013
13	13	014
14	14	015
15	15	016

PENKO How to...

Connect the SGM750 or SGM850 IND, BLT, CHK or MFL to a FLEX 2100, FLEX or FLEX 2ch. – 4ch.

Connect the SGM750 or SGM850 to a display

Set up the SGM750/SGM850:

Connect the SGM750/SGM850 to a PC using a USB-cable and open Pi Mach II and double click on **SGM750** or **SGM850**, then double click on **System Setup**, double click on **Communication**, double click on **RS232**. Set **Protocol** to “ASCII”, **Address** between “255”, **Stopbits** to “1”, **Parity** to “None”, **Baudrate** to “9600” and **Indicator** “1”. Click on **Apply** to save settings.

Note: Address 255 means the Net weight is constantly send to the display.

The screenshot displays the Penko software interface. On the left is a tree view of the device configuration. The path highlighted is: Penko > Device root > SGM750 Serial > 1.1.1.1 Name = > Live > System > System Setup > Communication > RS232. The right pane shows the configuration for the selected RS232 port, with the following settings:

Class: Penko.Device root.SGM750 Serial.System Setup.Communication.RS232	
Path: 1.1.1.3.3.5	
Protocol	ASCII
Address	255
Stopbits	1
Parity	None
Baudrate	9600
Indicator	1



About PENKO

Our design expertise include systems for manufacturing plants, bulk weighing, check weighing, force measuring and process control. For over 35 years, PENKO Engineering B.V. has been at the forefront of development and production of high-accuracy, high-speed weighing systems and our solutions continue to help cut costs, increase ROI and drive profits for some of the largest global brands, such as Cargill, Sara Lee, Heinz, Kraft Foods and Unilever to name but a few.

Whether you are looking for a simple stand-alone weighing system or a high-speed weighing and dosing controller for a complex automated production line, PENKO has a comprehensive range of standard solutions you can rely on.

Certifications

PENKO sets high standards for its products and product performance which are tested, certified and approved by independent expert and government organizations to ensure they meet – and even – exceed metrology industry guidelines. A library of testing certificates is available for reference on:

http://penko.com/nl/publications_certificates.html



PENKO Professional Services

PENKO is committed to ensuring every system is installed, tested, programmed, commissioned and operational to client specifications. Our engineers, at our weighing center in Ede, Netherlands, as well as our distributors around the world, strive to solve most weighing-system issues within the same day. On a monthly basis PENKO offers free training classes to anyone interested in exploring modern, high-speed weighing instruments and solutions. A schedule of training sessions is found on: www.penko.com/training

PENKO Alliances

PENKO's worldwide network: Australia, Belgium, Brazil, China, Denmark, Germany, Egypt, Finland, France, India, Italy, Netherlands, Norway, Poland, Portugal, Slovakia, Spain, Syria, Turkey, United Kingdom, South Africa, Slovakia Sweden, Switzerland and Singapore. A complete overview you will find on: www.penko.com/dealers

