PENKO Engineering B.V.

Your Partner for Fully Engineered Factory Solutions



How to... Parameters explanation and what do they do



Table of Contents

Neigher	. 4
ormat	. 5
Stable	. 6
Zero tracking	. 6
Range/Interval	. 7
ilter	. 8
Display	. 9



To set the parameters, connect the Indicator to the PC via an USB-cable. Open Pi Mach II and go to Environment. Click on Communication and set it to USB. Click Ok and it should load the device.

n ² SGM 700 serie, Device Version: 01.03, Build: 06, Serial: 13180057, Module Version: 00.00, Build: 00, Project: C:\Program Files\PI Mach II 72\				
File Project Environment View Tools Help				
🖌 💕 On-Line 🛛 🛞 Eirmware Update Manager 🗜 Program Builder 🧠 Flex Builder 🔲 Watches 🛛 🦪 E <u>w</u> it				
🛛 💻 Display 🗼 Control 🌒 Tasks 🛛 🏪 1/0 🚎 Indicator & Registers 🖚 Labels 🚆 Results 🛛 🏭 Printer Layout 👗 Printer Ticket 🛛 🕓 Clock 🗠 Scope 🛛 🏠 Manage				
□- Penko □- Device root □- SGM720 Ethernet	Class: Penko Path: 1			

Double click on **Enable Full setup** in the left window. In the right window the button **Enable Full setup** will appear, click on it.

🐔 SGM 700 serie, Device Version: 01.03, Build: 06, Serial: 13180057, Module Version: 00.00, Build: 00, Project: C:\Program Files\PI Mach II 72\				
File Project Environment View Tools Help				
💕 On-Line 🛛 🛞 Eirmware Update Manager 🐔 Program Builder 🥞 Flex Builder 🗐 🕁 atches 🛛 🛃 Exit				
📗 🖳 Display 🛛 🕨 Control 🌒 Tasks 🛛 🏪 1/0 📪 Indicator & Registers 📼 Labels 🚝	Results 💠 Printer Layout 📥 Printer Ticket 🛛 🕓 Clock 🗠 Scope 🛛 🏗 Manage			
⊡- Penko	Class: Penko.Device root.SGM720 Ethernet			
⊡- Device root	Path: 1.1.1			
- 1.1.1.1 Name =				
- 1.1.1.2 Start Quick setup	Enable Full setup			
⊕- Live				
⊡ System				
	Discover Import Properties (CSV)	Apply		
VSB open		//		



Click on the device you want to edit. In this case it is the SGM720. Double click on **System** Setup, double click on **Indicator** and double click on **Parameters**. Fill in the TAC code. The TAC (Traceable Access Code) code is the number of times the parameters has been accessed. Click on **Apply**.

🥇 SGM 700 serie, Device Version: 01.02, Build: 01, Serial: 13180057, Module Version: 00.00, Build: 00, Project: C:\Program Files\PI Mach II 72\			
File Project Environment View Tools Help			
💕 On-Line 🛛 🛞 Eirmware Update Manager 🔁 Program Builder 🧠 Flex Builder 🔲 Watches 🛛 🦪 Exit			
📗 🖤 Display 📔 🏲 Control 🌰 Tasks 🛛 🐫 1/0 📪 Indicator & Registers 📼 Labels 🚆	Results :::: Printer La	yout 🕭 Printer Ticket 🛛 🕓 🖸 Clock 🗠 Scope 🛛 🏠 Manage	
Penko Device root Graduate Control	Class: Penko.D Path: 1.1.1.3.	Device root.SGM720 Ethernet.System Setup.Indicator. 2.1	Parameters
- 1.1.1.1 Name =	ТАС	[0078]	
	Enter TAC	0	
Indicator			
	Discover	Import Properties (CSV)	Apply
ACTIVE USB USB open			//

When the correct TAC code is entered all Parameters are visible. The Parameters are categorized in: Weigher, Format, Stable ,Zero Tracking, Range/Interval, Filter and Display.

Weigher		
Penko Device root SGM720 Ethernet	Class: Penko.Device root.SC Path: 1.1.1.3.2.1.1	M720 Ethernet.System Setup.Indicator.Parameters.Weigher
- 1.1.1.1 Name = - 1.1.1.2 Start Quick setup - 1.1.1.3 Enable Full setup	Name	
⊕ Live ⊕ System	Maxload	99999,9 kg
⊡- System Setup ⊡- Service ≡	Operation mode	Industrial 💌
□ Indicator □ Parameters □ - 1.1.1.3.2.1.1 TAC = [0086] □ - 1.1.1.3.2.1.2 Enter TAC	Sample rate	1600/s
Weigher 1.1.1.3.2.1.1.1 Name = 1.1.1.3.2.1.1.2 Maxload = 99999,9 kg 1.1.1.3.2.1.1.3 Operation mode = Industrial 1.1.1.3.2.1.1.4 Sample rate = 1600/s ⊕ Format		
B- Stable B- Zero tracking		

Name: give the Indicator a name.



Maxload: fill in the weight the Indicator shows as the maximum load.

For example: if you are weighing 1000kg and the maximum amount you want to be show is 1005. Fill in 1005, above this amount the Indicator will show ======.

Operation mode: choose between Certified of Industrial.

Certified : sets parameters shuts as Zero tracking to certified settings.

Industrial: sets parameters shuts as Zero tracking to industrial settings.

Sample rate: the amount of samples the Indicator takes per second. The minimal setting is 20 samples per second, the maximum is 1600 samples per second.

Format

Penko Device root Device Toot Device Toot	*	Class: Penko.Device root.SG Path: 1.1.1.3.2.1.1.1	M720 Ethernet.System Setup.Indicator.Parameters.Weigher.Forma
- 1.1.1.1 Name = - 1.1.1.2 Start Quick setup - 1.1.1.3 Enable Full setup		Step	STEP 1
tive		Decimal point	00000.0
⊖ System Setup ⊕ System Setup	Ξ	Unit	kg
 □ Indicator □ Parameters □ 1.1.1.3.2.1.1 TAC = [0086] □ 1.1.1.3.2.1.2 Enter TAC □ Weigher □ 1.1.1.3.2.1.1.1 Name = □ 1.1.1.3.2.1.1.2 Maxload = 99999,9 kg □ 1.1.1.3.2.1.1.3 Operation mode = Industrial □ 1.1.1.3.2.1.1.4 Sample rate = 1600/s □ 1.1.1.3.2.1.1.1 Step = STEP 1 □ 1.1.1.3.2.1.1.1.2 Decimal point = 00000.0 			

Step: select the step size the Indicator makes while weighing.

For example: if you set step size to 1 the weigher weighs 10.1 - 10.2 - 10.3 etcetera. If you set the step size to 5 the weigher weighs 10.0 - 10.5 - 11.0 etcetera.

Decimal point: select the place for the decimal point.

Unit: fill in the weighing unit, for example: g, kg, ton, lbs. or liter.



Stable	
⊡-Penko ^ ⊡-Device root □ ⊡-SGM720 Ethernet	Class: Penko.Device root.S6M720 Ethernet.System Setup.Indicator.Parameters.Stable Path: 1.1.1.3.2.1.2
- 1.1.1.1 Name = - 1.1.1.2 Start Quick setup - 1.1.1.3 Enable Full setup	Stable range 0,2 kg
e- Live ⊕- System	Stable time 1,00 s
System Setup Service Indicator Indicator Parameters -1.1.1.3.2.1.1 TAC = [0086] -1.1.1.3.2.1.2 Enter TAC Weigher Stable -1.1.1.3.2.1.2.1 Stable range = 0,2 kg -1.1.1.3.2.1.2.2 Stable time = 1,00 s B Zero tracking Range/Interval B Filter B Display	

Stable range / Stable time: in this case the Stable range is set to 0,2 kg. This means that if the actual weight is within 0,2 kg of the targeted amount for more than 1 second (Stable time), the indicator will readout stable.

⊡-Penko	Â.	Class: Penko.Device root.S	GM720 Ethernet.System Setup.Indicator.Parameters.Zero tracking
SCM720 Ethornot		Path: 1.1.1.3.2.1.3	
_ J 1 1 1 Name -			
11112 Start Quick setup			
11112 Start Quick Setup	T	Fracking range	5,0 kg
THE LIVE			
T System		I racking step	0,5 kg
⊟- System Setup		Fracking time	100 c
. Service			1,00 5
⊡. Indicator	=		
🚊 Parameters			
🔄 Weigher			
Stable			
Er Zero tracking			
- 1.1.1.3.2.1.3.1 Tracking range = 5,0 kg			
- 1.1.1.3.2.1.3.2 Tracking step = 0,5 kg			
Range/Interval			
⊕ Filter			

Zero tracking

Tracking range / Tracking step / Tracking time: these 3 parameters work together and are best explained via an example. The settings above means that if the actual weight is between 0 and 5 kg, every second 0,5 kg is deducted from the weight until the weight reaches zero.

For example you can use these parameters for a manual weighing platform to rule out small bits of dirt.



Range/Interval		
Penko Device root GSM720 Ethernet 1111 Name =	Class: Penko.Device root Path: 1.1.1.3.2.1.4	.SGM720 Ethernet.System Setup.Indicator.Parameters.Range/Interva
- 1.1.1.2 Strat Quick setup - 1.1.1.3 Enable Full setup	Range	500 parts
⊕- Live ⊕- System	MaxStep	STEP 50
⊟- System Setup ⊕- Service	Mode	MULTI-RANGE
 □ Indicator □ Parameters □ 1.1.1.3.2.1.1 TAC = [0086] □ 1.1.1.3.2.1.2 Enter TAC ⊕ Weigher ⊕ Stable ⊕ Zero tracking ⊕ Range/Interval □ 1.1.1.3.2.1.4.1 Range = 500 parts □ 1.1.1.3.2.1.4.2 MaxStep = STEP 50 □ 1.1.3.2.1.4.3 Mode = MULTI-RANGE ⊕ Filter 		

Range: If the Decimal point is set to 0000.0 and the Range is 500 parts. The step size will increase as can be seen in the table below (Range * Step size).

Weighing range	Step size	Weighing step
0,0 – 50,0	1	0,1-0,2
50,0 - 100,0	2	50,2 - 50,4
100,0 - 250,0	5	100,5 - 101,0
250,0 - 500,0	10	251,0 - 252,0
500,0 - 1000,0	20	502,0 - 504,0
1000,0 - 2500,0	50	1005,0 - 1010,0

Max Step: set the maximum step size the indicator can increase, if the maximum step size you want is 1 kg. Set Max Step to Step 10 and the indicator weight will increase as can be seen in the table below.

Weighing range	Step size	Weighing step
0,0 – 50,0	1	0,1-0,2
50,0 - 100,0	2	50,2 - 50,4
100,0 - 250,0	5	100,5 - 101,0
250,0 – above	10	251,0 - 252,0

Mode: there are two settings, you can choose between Multi-Range and Multi-Interval.

Multi-Range: the Indicator will decrease in weight using the last used step size.

For example, If the Indicator is filling up to 250kg and the weight is increasing with 0,5kg (seen in the table below), the Indicator will use this step size (5) to decrease back to zero.



Weighing range	Step size	Weighing step
0,0 – 50,0	1	0,1-0,2
50,0 - 100,0	2	50,2 - 50,4
100,0 – 250,0	5	100,5 - 101,0
250 ,0- 0,0	5	250,0 - 249,5

Multi-Interval: the Indicator will decrease weight using the same step sizes as it used increasing weight.

For example, If the Indicator is filling up to 250kg and the weight is increasing with 0,5kg (seen in the table below), the Indicator will use the same steps to decrease to zero.

Weighing range	Step size	Weighing step
0,0, - 50,0	1	0,1-0,2
50,0 - 100,0	2	50,2 - 50,4
100,0 - 250,0	5	100,5 - 101,0
250,0 - 100,0	5	250,0 - 249,5
100,0 - 50,0	2	99,8 – 99,6
50,0 - 0,0	1	49,9 - 49,8

Filter

Penko Device root Device Toot SGM720 Ethernet	Class: Penko.Device root.SGM720 Ethernet.System Setup.Indicator.Parameters.Filter Path: 1.1.1.3.2.1.5	
- 1.1.1.1 Name = - 1.1.1.2 Start Quick setup - 1.1.1.3 Enable Full setup	Overall filter	0 dB
⊕- Live ⊕- Svstem	Filter type	Dynamic 💌
System Setup Service	Cut Off	2,5 Hz
	Moving Average	10 Hz

Overall filter: set the overall filter to effect all indicator signals used in the device. OdB means no effect and –42dB is the strongest damping.

Filter type: choose between None, Dynamic filter or Static filter.

None: choose None if you don't want a filter

Dynamic filter: choose Dynamic filter when the weighing signal is changing fast.



Static filter: choose Static filter when the weighing signal is slowly changing.

Cut Off: any frequency (that can interfere with the weighing signal) above the selected value will be filtered out.

Moving Average: if you have frequencies from outside the weighing unit that interfere with the weighing signal, you can filter these frequencies out by using the Moving Average filter. You can see these frequencies by using the scope function in Pi.

For example, if there are three frequencies that need to be filtered out, and those frequencies are 70Hz, 35Hz and 10Hz. Select the highest frequency that can be divided 70Hz, 35Hz and 10Hz, which is 5Hz.

5Hz is 200msec, if the Sample rate is selected to 1600 sample per sec. It means that during the 200msec it will measure 320 samples. From these 320 samples the Indicator will calculate the average and this will be the average weighing signal.

The higher the Moving Average is, the faster the Indicator is weighing.

Display

	- 1		
□ Penko	A	Class: Penko.Device root.SG	M720 Ethernet.System Setup.Indicator.Parameters.Display
⊡ Devic	ce root	Path: 1.1.1.3.2.1.6	
E. 2	GM720 Ethernet		
	- 1.1.1.2 Start Quick setup	Rate	25/c
	1.1.1.3 Enable Full setup	hute	23/3
	- Live	Display Net/Gross:Filter range	10.0 kg
	- System		
Ē	- System Setup	Display Net/Gross:Filter damping	0 dB
	E Service		o do
	⊡- Indicator	Display Net/Gross:Zero suppress	0,0 kg
	🖻 Parameters		
	- 1.1.1.3.2.1.1 TAC = [0086]	Indicator	WEIGHER
	- 1.1.1.3.2.1.2 Enter TAC		
	The Terro tracking		
	E Pango/Inton/al		
	±. Filter		
	B-Display		
	1.1.1.3.2.1.6.2 Display Net/Gross:Filter range = 10,		
	- 1.1.1.3.2.1.6.3 Display Net/Gross:Filter damping =		
	- 1.1.1.3.2.1.6.4 Display Net/Gross:Zero suppress = (
	E caloradon		

Rate: the refresh rate of the display in times per second.

Display Net/Gross: Filter range: this filter works together with the Filter damping. If the entered value is 10kg, and the actual value is between +10 or -10 kg of the total Net or gross. The Display Net/Gross: Filter damping will be active.

Display Net/Gross: Filter damping: this filter works together with the Filter range. If the entered value is 10kg, and the actual value is between +10 or -10 kg of the total Net or gross. The Display Net/Gross: Filter damping will be active. 0dB is no damping and -42dB is the strongest damping.



Display Net/Gross: Zero suppress: zero suppress means that any weight below the filled in value will be forced to zero.

For example, if the filled in weight is 5kg and the actual weight is 3kg, the Indicator will set itself to zero.

Indicator: select which value you want the Indicator to show on the display.





About PENKO

Our design expertise include systems for manufacturing plants, bulk weighing, check weighing, force measuring and process control. For over 35 years, PENKO Engineering B.V. has been at the forefront of development and production of high-accuracy, high-speed weighing systems and our solutions continue to help cut costs, increase ROI and drive profits for some of the largest global brands, such as Cargill, Sara Lee, Heinz, Kraft Foods and Unilever to name but a few.

Whether you are looking for a simple stand-alone weighing system or a high-speed weighing and dosing controllerforacomplexautomated production line, PENKO has a comprehensive range of standard solutions you can rely on.

Certificeëringen

PENKO sets high standards for its products and product performance which are tested, certified and approved by independent expert and government organizations to ensure they meet - and even - exceed metrology industry guidelines. A library of testing certificates is available for reference on:

http://penko.com/nl/publications_certificates.html

PENKO Profesional Services

PENKO is committed to ensuring every system is installed, tested, programmed, commissioned and operational to client specifications. Our engineers, at our weighing center in Ede, Netherlands, as well as our distributors around the world, strive to solve most weighing-system issues within the same day. On a monthly basisPENKO offers free training classes to anyone interested in exploring modern, high-speed weighing instruments and solutions. A schedule of training sessions is found on: www.penko.com/training



an ETC Company

PENKO Allianties

PENKO's worldwide network: Australia, Belgium, Brazil, China, Danmark, Germany, Egypt, Finland, France, India, Italy, Netherlands, Noorway, Portugal, Slowakia, Spain, Syrië, Turkey, United Kingdom, south Afrika, sweden en Switserland. A complete overview you will find on: **www. penko.com/dealers**

PENKO Engineering BV = Schutterweg 35, NL 6718XC Ede = Tel +31 (0) 318 525630 = Fax +31 (0) 318 52971 = info@penko.com Web = www.penko.com = Copyright © 2014 ETC All rights reserved.